

COMMANDING OFFICER
NETPDTC
6490 SAUFLEY FIELD RD
PENSACOLA, FL 32509-5237

ERRATA #1

10 May 1993

Specific Instructions and Errata for
Training Manual and
Nonresident Training Course

ENGINEMAN 3, NAVEDTRA 80539

1. No attempt has been made to issue corrections for errors in typing, punctuation, etc., that do not affect your ability to answer the question or questions.
2. To receive credit for deleted questions, show this errata to your local course administrator (ESO/scorer). The local course administrator is directed to correct the course and the answer key by indicating the question deleted.
3. Assignment Booklet, NAVEDTRA 80539.

Delete the following questions, and leave the corresponding spaces blank on the answer sheets:

<u>Questions</u>	<u>Questions</u>
4-60	4-62
4-61	4-63

Make the following changes:

<u>Question</u>	<u>Change</u>
3-11	In the question, line 2, change the word "camshaft" to read "crankshaft."
Pg 11	Delete learning objective: Point out the functions of the crankshaft, cam followers, and lash adjusters.

4. Textbook, Engineman 3, NAVEDTRA 10539.

<u>Page</u>	<u>Column</u>	<u>Lines</u>	<u>Change</u>
-------------	---------------	--------------	---------------

9-28	Right	6 and 7	Change to read: This is because diesel engines can run at speeds in excess of 2000 rpm.
11-14	Right	Par. 2 line 1	Change "starboard" to read "shipboard."